



SEA-BIRD ELECTRONICS, INC.

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

47527

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 8/6/2007

Contact Paul Coenen

PO Number TBD

Serial Number 37SMP35194-3531

Model Number SBE 37SMP

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Replace Antifoulant Device(s).

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
3. Calibrated the pressure sensor.
4. Installed NEW SBE 37 SMP/IMP/SIP Duct w/ Air Bleed Vent. *
5. Installed NEW Anti-foulant device(s).
6. Performed complete system check and full diagnostic evaluation.

Special Notes:

* Please see field service bulletin No. 11.