



Sea-Bird Electronics, Inc.

1808 136th Place NE, Bellevue, Washington 98005 USA
Website: <http://www.seabird.com>

FAX: (425) 643-9954

Tel: (425) 643-9866
Email: seabird@seabird.com

Service Report

SBE Job Number: 44053R

Date: 13, September 2006

Customer: Monterey Bay Aquarium Research Institute

Customer Identified Problem:

1. Calibrate SBE 37IMP MICROCATs, S/N 37IMP35194-3532, 37IMP35194-3533, and 37IMP35194-3535.
2. Calibrate and verify operation of SBE 37IMP MICROCAT, S/N 37IMP35194-3534.

Services Performed:

1. Calibrations performed on SBE 37IMP MICROCATs, S/N 37IMP35194-3532, 37IMP35194-3533, and 37IMP35194-3535.
Updated the EPROMs to version 2.3a.
Post calibrated the temperature and conductivity sensors.
Calibrated the pressure sensors.
Replaced the anti-foulant cylinders. *As requested*
Performed full diagnostic evaluations.
2. Calibrations and services performed on SBE 37IMP MICROCAT, S/N 37IMP35194-3534.
Updated the EPROM to version 2.3a.
Post calibrated the temperature and conductivity sensors.
Calibrated the pressure sensor.
Replaced the anti-foulant cylinders. *As requested*
Performed full diagnostic evaluation, no excessive current draw was detected.