



Sea-Bird Electronics, Inc.

1808 136th Place NE, Bellevue, Washington 98005 USA
Website: <http://www.seabird.com>

FAX: (425) 643-9954

Tel: (425) 643-9866
Email: seabird@seabird.com

Service Report

SBE Job Number: 43270

Date: 22, June 2006

Customer: Monterey Bay Aquarium Research Institute

Customer Identified Problem:

1. Upgrade and calibrate SBE 37SMP MICROCAT, S/N 37SMP35635-3318.

Services Performed:

1. Calibrations and services performed on SBE 37SMP MICROCAT, S/N 37SMP35635-3318.
 - Updated the EPROM to version 2.6b.
 - Replaced the standard 4-Pin I/O connector with a *new* wet-pluggable 4-Pin I/O connector, as requested.
 - Replaced the main piston "O"-Rings.
 - Performed hydrostatic pressure test.
 - Post calibrated the temperature and conductivity sensors.
 - Calibrated the pressure sensor.
 - Performed full diagnostic evaluation.