

**SEA-BIRD ELECTRONICS, INC.**

13431 NE 20th Street
Bellevue, Washington 98005 USA

Phone +1-425-643-9866
Fax +1-425-643-9954
www.seabird.com

SERVICE REPORT

Service Request
Date

1005500596
09-DEC-2016

CUSTOMER INFORMATION

Name: MBARI - MONTEREY BAY AQUARIUM RESEARCH INSTITUTE
Account : 40279834
CHRIS WAHL
CWAHL@MBARI.ORG
831 775 1746

PO Number:
1111868

Bill To Address

ACCOUNTS PAYABLE;7700 SANDHOLDT RD.;
MOSS LANDING,CA,95039-9644,US

Ship To Address

7700 SANDHOLDT ROAD;BUILDING A;
MOSS LANDING,CA,95039-9644,US

PRODUCT INFORMATION

Item: 37SMP.LEGACY

Item Description: (LEGACY) SBE 37SMP MicroCAT

Serial: 37SMP35635-3318

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.

Perform Routine Calibration Service.

Perform hydrostatic pressure test.

Replace Antifoulant Device(s).

Problems Found:

The 4-pin I/O bulkhead connector was found to have corrosion damage.

Services Performed:

Perform initial diagnostic evaluation.

Performed "POST" cruise calibration.

Performed pressure calibration.

Installed NEW four pin bulkhead connector(s).

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed complete system check and full diagnostic evaluation.

Installed NEW AF24173 Anti-foulant cylinder(s).

Item	Item Description	Qty
PCAL37	EXTRA CHARGE TO CALIBRATE SBE 37 PRESSURE CHANNEL (FRRF)	1
SERVICE37	COMPLETE EXTERNAL INSPECTION. TEST ALL FUNCTIONS. CALIBRATE C & T, C&P AND RECAL IF NECESSARY. REPLACE END CAP O-RINGS A (FRRF)	1
REPLACEAF	EXTRA CHARGE TO INSTALL ONE ANTIFOULANT DEVICE, INCLUDES ONE 801542.1. (FRRF)	2

Unbilled Items

**SEA-BIRD ELECTRONICS, INC.**

13431 NE 20th Street
Bellevue, Washington 98005 USA

Phone +1-425-643-9866
Fax +1-425-643-9954
www.seabird.com

SERVICE REPORT

Service Request
Date

1005500596
09-DEC-2016

Item	Item Description	Qty
801542.1	AF24173 ANTI-FOULANT, SINGLE CYLINDER, V2	2
172021	CONN, MCBH-4MP(WB), TI, 1/2-20,IMPULSE/33022D	1