



Sea-Bird Electronics, Inc.

1808 136th Place NE, Bellevue, Washington 98005 USA
Website: <http://www.seabird.com>

FAX: (425) 643-9954

Tel: (425) 643-9866
Email: seabird@seabird.com

Service Report

SBE Job Number: 44024

Date: 5, September 2006

Customer: Monterey Bay Aquarium Research Institute

Customer Identified Problem:

1. Calibrate SBE 37SMP MICROCAT, S/N 37SMP35194-3531.

Services Performed:

1. Calibrations performed on SBE 37SMP MICROCAT, S/N 37SMP35194-3531.
Updated the EPROM to version 2.6b.
Replaced the connector with a **new** wet-pluggable connector. *As Requested*
Replaced the main piston "O"-Rings.
Performed hydrostatic pressure test.
Post calibrated the temperature and conductivity sensors.
Calibrated the pressure sensor.
Installed **new** AF24173 Antifoulant Devices. *As Requested*
Performed full diagnostic evaluation.