



Electronic Measurement Service

1751 Fortune Drive, Suite J
San Jose, CA 95131-1705
408/954-1463

Invoice

DATE	INVOICE #
1/24/2019	6465

BILL TO:

Monterey Bay Aquarium Research Institute
Attention: Accounts Payable
7700 Sandholdt Road
Moss Landing, CA 95039-9644

SHIP TO:

Monterey Bay Aquarium Research Institute
Attention: Receivung
7700 Sandholdt Road
Moss Landing, CA 95039-9644

P.O. NO.	TERMS	SHIP VIA
Verbal - Duane	Credit Card	FedEx ground /f

ITEM	QTY	DESCRIPTION	JOB/PKG LIS...	UNIT PRICE	TOTAL PRICE
Parts	20	Circuit board for Genesys 2.4KW power supply Conformal Coated	31934	40.00	800.00T
RP Repair	1	Model: GEN 40-60-LAN-1P230 SN: LOC-350A004-0001 Labor (Repaired)	31909	500.00	500.00
Parts	1	Replacement Parts Subtotal		88.00	88.00T 588.00
RP Repair	1	Model: GEN 40-60-LAN-1P230 SN: LOC-426A071-0003 Labor (Repaired)	31908	350.00	350.00
Parts	1	Replacement Parts Subtotal		469.00	469.00T 819.00
Shipping		Shipping: Fedex Ground F/C Tracking 774185525570 & 774301486491		0.00	0.00
			Subtotal	\$2,207.00	

Federal Tax ID: 546-86-6557

Sales Tax (7.75%) \$105.17

Total (USD) \$2,312.17