

	Doc or ECO #:	ECO-70892-003	Date:	04/28/2021	Author:	SL
	Rev. #:	A				
Engineering Change Order (ECO)	Engineering Approval:	aeg	Date:	4/28/2021	Quality Approval:	aeg

P/N #:	70892	Effective Date:	April 28, 2021
Title:	Pro 5 Mission Specialist Shield Sticker Correction		

1.0 Purpose / Summary

- The purpose of this ECO is to correct the part number and upgrade the material used on the Mission Specialist Shield sticker that is adhered to the Pro 5

2.0 Parts Affected

Part Number	Notes	Removed	Added	Modified	REV
70892	Top Level Kit	☐	☐	☒	F
70936	100% Scale Shield Sticker	☒	☐	☐	A
73296	50% Scale Shield Sticker	☐	☒	☐	A

3.0 Detail

- The Pro 5 Bill of Materials was using the incorrect part number (70936) for the Mission Specialist Shield Sticker adhered to the Float Block.
- Part Number (73296) which is a 50% scale of the Defender version (70936) has replaced (70936) in the Bill of Materials for the Pro 5
- The stickers material has been upgraded to Poly Carbonate from Vinyl to increase durability

4.0 Disposition of Material

- Dispose of any remaining vinyl stickers and begin using the Poly Carbonate Version

5.0 Action Items

Action	Department	Acknowledgement Initials
Update BOMs	Engineering	SL
Update Epicor	Purchasing	SL
Update GA	Engineering	MW

	Doc or ECO #:	ECO-70892-003	Date:	04/28/2021	Author:	SL
	Rev. #:	A				
Engineering Change Order (ECO)	Engineering Approval:	aeg	Date:	4/28/2021	Quality Approval:	aeg

6.0 Modified / Referenced Documents:

Document	Current Revision
BOM-70892	F

7.0 Revision History

Date Revised (mm-dd-yyyy)	Location of Change (section, paragraph no., step no., etc.)	Description of Change Made	Name of Person making the Change
4/28/2021	All	Init	SL