

Engineering Department

Engineering Change Order (ECO)

ECO #: PLB-002C-001

Effective Date: January 19, 2016

Title: PLB-002C Hole Change

Author: Steve Lash
 Engineering Approval: AEG
 Operations Approval: JJV

Date: January 19, 2016
 Date: January 19, 2016
 Date: January 19, 2016

Summary:

Hole diameters on part PLB-002C have been adjusted to improve fit of part.

Parts Affected:

Part Number	Notes	Removed	Added	Modified
PLB-002C	Drawing updated to REV-B. Hole diameters have been adjusted for assembly.	☐	☐	☒

Detail:

Secondary inspection of part PLB-002C by an external manufacturer has revealed the through-hole dimensions to be incorrect on the Rev A drawing. Verification with historical data, and manufacturer set-up sheets has revealed the small and large through holes should be of diameters 0.116" and 0.156" respectively. Attached drawing Rev B has been issued to address this change.

Action Item:

Action	Department	Acknowledgement Initials
Send Rev B drawing to external manufacturers	Operations/Purchasing	Click here to enter text.

Modified / Referenced Documents:

Document	Current Revision
PLB-002C Drawing	B

-- END OF ORDER --