


Data Report for Device 1484_1482 from Thu Mar 16 16:46:44 UTC 2006 to Fri Mar 17 16:46:44 UTC 2006 sorted by SIAM timestamp




SIAM Timestamp	SIAM Timestamp converted to time/date (PST)	Packet Sequence Number	String
1142527878736	2006-03-16 08:51:18 -0800	373	\$PEDATA, P1018.76, T24.71, H57.76, GFL0.00, GFH-0.13, C290.34, TC0.00, *3754
1142528478755	2006-03-16 09:01:18 -0800	374	\$PEDATA, P1019.71, T24.65, H57.95, GFL0.00, GFH0.13, C289.54, TC0.00, *3719
1142529079902	2006-03-16 09:11:19 -0800	375	\$PEDATA, P1019.56, T24.29, H58.72, GFL0.00, GFH0.00, C295.18, TC0.00, *3711
1142529678736	2006-03-16 09:21:18 -0800	376	\$PEDATA, P1019.92, T25.01, H57.64, GFL0.00, GFH0.13, C290.66, TC0.00, *3704
1142530278735	2006-03-16 09:31:18 -0800	377	\$PEDATA, P1020.01, T25.06, H57.84, GFL0.00, GFH0.00, C290.66, TC0.00, *3689
1142530879745	2006-03-16 09:41:19 -0800	378	\$PEDATA, P1019.90, T24.85, H58.35, GFL0.14, GFH0.00, C292.76, TC0.00, *3716
1142531478735	2006-03-16 09:51:18 -0800	379	\$PEDATA, P1018.94, T25.08, H58.22, GFL0.00, GFH0.00, C290.66, TC0.00, *3703
1142532078735	2006-03-16 10:01:18 -0800	380	\$PEDATA, P1019.21, T25.54, H57.52, GFL0.00, GFH0.00, C287.76, TC0.00, *3704
1142532679560	2006-03-16 10:11:19 -0800	381	\$PEDATA, P1020.44, T25.69, H57.10, GFL0.00, GFH0.00, C285.67, TC0.00, *3699
1142533278756	2006-03-16 10:21:18 -0800	382	\$PEDATA, P1019.51, T25.98, H56.72, GFL-0.14, GFH-0.25, C284.06, TC0.00, *3808
1142533878751	2006-03-16 10:31:18 -0800	383	\$PEDATA, P1019.67, T26.24, H56.66, GFL0.00, GFH0.00, C284.06, TC0.00, *3706
1142534478744	2006-03-16 10:41:18 -0800	384	\$PEDATA, P1020.74, T26.26, H56.66, GFL0.00, GFH0.13, C288.09, TC0.00, *3709
1142535078737	2006-03-16 10:51:18 -0800	385	\$PEDATA, P1020.62, T26.10, H56.90, GFL0.00, GFH0.00, C287.12, TC0.00, *3685
1142535680322	2006-03-16 11:01:20 -0800	386	\$PEDATA, P1019.75, T26.39, H56.81, GFL0.00, GFH0.00, C286.15, TC0.00, *3710
1142536278778	2006-03-16 11:11:18 -0800	387	\$PEDATA, P1019.85, T26.54, H56.76, GFL-0.14, GFH-0.13, C285.99, TC0.00, *3822
1142536878738	2006-03-16 11:21:18 -0800	388	\$PEDATA, P1019.92, T26.65, H56.68, GFL0.00, GFH0.00, C286.15, TC0.00, *3713
1142537478740	2006-03-16 11:31:18 -0800	389	\$PEDATA, P1019.97, T26.77, H56.73, GFL0.00, GFH-0.13, C285.99, TC0.00, *3777
1142538078737	2006-03-16 11:41:18 -0800	390	\$PEDATA, P1019.79, T26.43, H57.29, GFL-0.14, GFH0.13, C288.41, TC0.00, *3767
1142538678746	2006-03-16 11:51:18 -0800	391	\$PEDATA, P1019.74, T26.42, H57.73, GFL0.00, GFH-0.25, C293.56, TC0.00, *3760
1142539278742	2006-03-16 12:01:18 -0800	392	\$PEDATA, P1018.03, T27.02, H57.02, GFL0.00, GFH0.00, C287.12, TC0.00, *3683
1142539879910	2006-03-16 12:11:19 -0800	393	\$PEDATA, P1019.21, T27.25, H56.88, GFL0.00, GFH-0.13, C286.96, TC0.00, *3762
1142540478744	2006-03-16 12:21:18 -0800	394	\$PEDATA, P1016.15, T27.45, H56.81, GFL0.00, GFH0.13, C287.76, TC0.00, *3711
1142541078737	2006-03-16 12:31:18 -0800	395	\$PEDATA, P1017.03, T27.18, H57.64, GFL-0.14, GFH-0.13, C290.83, TC0.00, *3798
1142541678736	2006-03-16 12:41:18 -0800	396	\$PEDATA, P1019.13, T27.17, H57.80, GFL0.00, GFH0.00, C293.08, TC0.00, *3699
1142542279711	2006-03-16 12:51:19 -0800	397	\$PEDATA, P1019.20, T27.27, H58.01, GFL0.00, GFH-0.13, C293.89, TC0.00, *3750
1142542878745	2006-03-16 13:01:18 -0800	398	\$PEDATA, P1020.13, T27.09, H58.11, GFL0.00, GFH0.13, C291.79, TC0.00, *3697
1142543478897	2006-03-16 13:11:18 -0800	399	\$PEDATA, P1017.73, T26.57, H61.26, GFL0.14, GFH0.63, C291.15, TC0.00, *3711
1142544078737	2006-03-16 13:21:18 -0800	400	\$PEDATA, P1016.11, T27.46, H58.53, GFL0.00, GFH-0.13, C292.76, TC0.00, *3750
1142544678734	2006-03-16 13:31:18 -0800	401	\$PEDATA, P1018.38, T27.65, H57.42, GFL0.00, GFH0.00, C288.25, TC0.00, *3709
1142545279434	2006-03-16 13:41:19 -0800	402	\$PEDATA, P1017.50, T26.16, H63.82, GFL0.00, GFH0.13, C296.63, TC0.00, *3703
1142545878742	2006-03-16 13:51:18 -0800	403	\$PEDATA, P1017.91, T26.92, H60.30, GFL0.00, GFH-0.13, C292.44, TC0.00, *3742
1142546480657	2006-03-16 14:01:20 -0800	404	\$PEDATA, P1017.51, T26.04, H64.46, GFL0.00, GFH0.13, C284.86, TC0.00, *3704
1142547078741	2006-03-16 14:11:18 -0800	405	\$PEDATA, P1018.06, T27.18, H60.27, GFL0.00, GFH0.13, C287.12, TC0.00, *3698
1142547678741	2006-03-16 14:21:18 -0800	406	\$PEDATA, P1017.62, T26.29, H63.91, GFL0.00, GFH0.00, C285.19, TC0.00, *3705
1142548278736	2006-03-16 14:31:18 -0800	407	\$PEDATA, P1018.05, T27.14, H61.34, GFL0.00, GFH0.13, C292.44, TC0.00, *3693
1142548878743	2006-03-16 14:41:18 -0800	408	\$PEDATA, P1016.81, T26.87, H59.73, GFL0.00, GFH0.00, C289.05, TC0.00, *3713
1142549478746	2006-03-16 14:51:18 -0800	409	\$PEDATA, P1017.19, T25.64, H65.91, GFL0.14, GFH0.00, C291.47, TC0.00, *3710
1142550078886	2006-03-16 15:01:18 -0800	410	\$PEDATA, P1016.72, T26.67, H62.93, GFL0.00, GFH0.25, C294.21, TC0.00, *3708
1142550679947	2006-03-16 15:11:19 -0800	411	\$PEDATA, P1016.80, T26.84, H61.52, GFL0.00, GFH0.13, C291.31, TC0.00, *3695
1142551278736	2006-03-16 15:21:18 -0800	412	\$PEDATA, P1017.00, T25.36, H65.38, GFL0.00, GFH0.13, C284.38, TC0.00, *3701
1142551878736	2006-03-16 15:31:18 -0800	413	\$PEDATA, P1019.44, T25.82, H64.40, GFL0.00, GFH0.00, C291.63, TC0.00, *3696
1142552478736	2006-03-16 15:41:18 -0800	414	\$PEDATA, P1016.75, T26.72, H61.87, GFL0.00, GFH0.00, C291.79, TC0.00, *3712
1142553078876	2006-03-16 15:51:18 -0800	415	\$PEDATA, P1016.82, T26.83, H61.36, GFL0.00, GFH0.00, C294.85, TC0.00, *3706
1142553678736	2006-03-16 16:01:18 -0800	416	\$PEDATA, P1015.91, T27.09, H60.67, GFL0.00, GFH-0.13, C292.92, TC0.00, *3752
1142554278732	2006-03-16 16:11:18 -0800	417	\$PEDATA, P1015.97, T27.20, H60.37, GFL0.00, GFH0.13, C291.63, TC0.00, *3700
1142554878735	2006-03-16 16:21:18 -0800	418	\$PEDATA, P1014.91, T27.17, H60.27, GFL0.00, GFH-0.13, C292.92, TC0.00, *3746
1142555478752	2006-03-16 16:31:18 -0800	419	\$PEDATA, P1016.22, T27.53, H59.66, GFL0.00, GFH-0.13, C292.76, TC0.00, *3755
1142556078767	2006-03-16 16:41:18 -0800	420	\$PEDATA, P1014.57, T28.30, H58.65, GFL0.00, GFH-0.13, C294.37, TC0.00, *3754
1142556678916	2006-03-16 16:51:18 -0800	421	\$PEDATA, P1015.54, T28.08, H58.75, GFL0.00, GFH0.00, C287.60, TC0.00, *3707
1142557278751	2006-03-16 17:01:18 -0800	422	\$PEDATA, P1016.14, T27.34, H59.95, GFL0.00, GFH0.13, C291.15, TC0.00, *3704
1142557879297	2006-03-16 17:11:19 -0800	423	\$PEDATA, P1016.03, T27.25, H60.31, GFL0.00, GFH0.13, C294.05, TC0.00, *3686
1142558478745	2006-03-16 17:21:18 -0800	424	\$PEDATA, P1017.05, T27.13, H60.49, GFL0.00, GFH0.13, C291.47, TC0.00, *3698
1142559079039	2006-03-16 17:31:19 -0800	425	\$PEDATA, P1019.34, T25.70, H63.45, GFL0.00, GFH0.00, C281.48, TC0.00, *3698
1142559680150	2006-03-16 17:41:20 -0800	426	\$PEDATA, P1016.36, T26.00, H63.02, GFL0.00, GFH0.13, C288.57, TC0.00, *3695
1142560278751	2006-03-16 17:51:18 -0800	427	\$PEDATA, P1016.51, T26.22, H62.21, GFL0.00, GFH0.00, C288.57, TC0.00, *3692
1142560878746	2006-03-16 18:01:18 -0800	428	\$PEDATA, P1016.59, T26.42, H61.55, GFL0.00, GFH-0.25, C290.34, TC0.00, *3748
1142561478866	2006-03-16 18:11:18 -0800	429	\$PEDATA, P1016.52, T26.33, H61.79, GFL0.00, GFH-0.25, C292.92, TC0.00, *3753
1142562078786	2006-03-16 18:21:18 -0800	430	\$PEDATA, P1015.39, T26.14, H61.92, GFL0.00, GFH0.13, C294.21, TC0.00, *3697
1142562678736	2006-03-16 18:31:18 -0800	431	\$PEDATA, P1014.76, T26.79, H60.53, GFL0.00, GFH0.00, C286.15, TC0.00, *3704
1142563278865	2006-03-16 18:41:18 -0800	432	\$PEDATA, P1015.58, T26.52, H61.03, GFL0.00, GFH0.00, C289.86, TC0.00, *3703
1142563878766	2006-03-16 18:51:18 -0800	433	\$PEDATA, P1017.06, T27.08, H59.82, GFL0.14, GFH0.00, C292.76, TC0.00, *3712

1142564043439	2006-03-16 18:54:03 -0800	434	<SRVC_MD> powerOnDelaySec=0 instrumentName=UNKNOWN nominalCurrentMa=1000 className=moos.devices.msp430.MSP430\$Attributes serviceName=MSP430 (sidearm4.22) parentID=1482 currentLimitMa=500 turnsSetpoint=0 sampleSchedule=R */0 */10 */0 */0 * * * * GMT * setTurns=false extendedVersion=UNK frameworkVersion=\$Name: march14_2006 \$ UUID=e2640737-65f5-11da-950b-00306e389969 powerPolicy=ALWAYS timeSynch=false maxSampleTries=3 isiID=1484 sampleTimeoutMsec=10000 commPowerPolicy=ALWAYS serviceStatus=2 startDelayMsec=500 </SRVC_MD> <DEV_MD> \$PSID, V2.3.1-Q [Mar 12 2004], *1811 \$PALEVEL, PL0.000000, PH0.000000, TL0.000000, TH0.000000, HL0.000000, HH0.000000, GF \$PAMASK, 00, *729 \$PALARM, 00, *729 </DEV_MD> <DOC_MD> unable to access XML file </DOC_MD>
1142564046060	2006-03-16 18:54:06 -0800	435	\$PEDATA, P1016.05, T27.20, H59.64, GFL-0.14, GFH0.00, C284.70, TC0.00, *3744
1142564647996	2006-03-16 19:04:07 -0800	436	\$PEDATA, P1013.72, T26.98, H59.84, GFL0.00, GFH-0.13, C276.81, TC0.00, *3763
1142565246035	2006-03-16 19:14:06 -0800	437	\$PEDATA, P1013.86, T27.16, H59.57, GFL0.00, GFH-0.13, C285.83, TC0.00, *3761
1142565846041	2006-03-16 19:24:06 -0800	438	\$PEDATA, P1013.85, T27.09, H59.53, GFL0.00, GFH-0.13, C277.61, TC0.00, *3755
1142566446034	2006-03-16 19:34:06 -0800	439	\$PEDATA, P1015.75, T26.79, H59.84, GFL-0.14, GFH0.00, C276.97, TC0.00, *3775
1142567046077	2006-03-16 19:44:06 -0800	440	\$PEDATA, P1015.64, T26.59, H60.19, GFL0.00, GFH-0.13, C276.97, TC0.00, *3760
1142567822710	2006-03-16 19:57:02 -0800	441	<SRVC_MD> powerOnDelaySec=0 instrumentName=UNKNOWN nominalCurrentMa=1000 className=moos.devices.msp430.MSP430\$Attributes serviceName=MSP430 (sidearm4.22) parentID=1482 currentLimitMa=500 turnsSetpoint=0 sampleSchedule=R */0 */10 */0 */0 * * * * GMT * setTurns=false extendedVersion=UNK frameworkVersion=\$Name: march14_2006 \$ UUID=e2640737-65f5-11da-950b-00306e389969 powerPolicy=ALWAYS timeSynch=false maxSampleTries=3 isiID=1484 sampleTimeoutMsec=10000 commPowerPolicy=ALWAYS serviceStatus=2 startDelayMsec=500 </SRVC_MD> <DEV_MD> \$PSID, V2.3.1-Q [Mar 12 2004], *1811 \$PALEVEL, PL0.000000, PH0.000000, TL0.000000, TH0.000000, HL0.000000, HH0.000000, GF \$PAMASK, 00, *729 \$PALARM, 00, *729 </DEV_MD> <DOC_MD> unable to access XML file </DOC_MD>
1142567824350	2006-03-16 19:57:04 -0800	442	\$PEDATA, P1015.34, T26.08, H60.94, GFL0.00, GFH0.00, C277.77, TC0.00, *3704
1142568650361	2006-03-16 20:10:50 -0800	443	<SRVC_MD> powerOnDelaySec=0 instrumentName=UNKNOWN nominalCurrentMa=1000 className=moos.devices.msp430.MSP430\$Attributes serviceName=MSP430 (sidearm4.22) parentID=1482 currentLimitMa=500 turnsSetpoint=0

				<pre>sampleSchedule=R */0 */10 */0 */0 * * * GMT * setTurns=false extendedVersion=UNK frameworkVersion=\$Name: march14 2006 \$ UUID=e2640737-65f5-11da-950b-00306e389969 powerPolicy=ALWAYS timeSynch=false maxSampleTries=3 isiID=1484 sampleTimeoutMsec=10000 commPowerPolicy=ALWAYS serviceStatus=2 startDelayMsec=500 </SRVC_MD> <DEV_MD> \$PSID, V2.3.1-Q [Mar 12 2004], *1811 \$PALEVEL, PL0.000000, PH0.000000, TL0.000000, TH0.000000, HL0.000000, HH0.000000, GF: \$PAMASK, 00, *729 \$PALARM, 00, *729 </DEV_MD> <DOC_MD> unable to access XML file </DOC_MD></pre>
1142568652699	2006-03-16 20:10:52 -0800	444		\$PEDATA, P1015.81, T26.85, H59.53, GFL0.00, GFH0.25, C287.76, TC0.00, *3721
1142569252608	2006-03-16 20:20:52 -0800	445		\$PEDATA, P1014.87, T27.00, H59.02, GFL0.00, GFH0.00, C288.57, TC0.00, *3701
1142569852618	2006-03-16 20:30:52 -0800	446		\$PEDATA, P1014.65, T26.58, H59.75, GFL-0.14, GFH0.13, C290.02, TC0.00, *3756
1142570452614	2006-03-16 20:40:52 -0800	447		\$PEDATA, P1016.88, T26.86, H59.37, GFL0.00, GFH0.13, C288.41, TC0.00, *3722
1142571052660	2006-03-16 20:50:52 -0800	448		\$PEDATA, P1016.32, T26.01, H60.62, GFL0.00, GFH-0.13, C291.15, TC0.00, *3728
1142571652615	2006-03-16 21:00:52 -0800	449		\$PEDATA, P1015.18, T25.89, H60.66, GFL0.00, GFH0.13, C292.11, TC0.00, *3702
1142572252616	2006-03-16 21:10:52 -0800	450		\$PEDATA, P1013.00, T25.82, H60.87, GFL0.00, GFH0.00, C290.66, TC0.00, *3691
1142572852636	2006-03-16 21:20:52 -0800	451		\$PEDATA, P1015.10, T25.77, H60.89, GFL0.00, GFH0.00, C295.50, TC0.00, *3698
1142573452626	2006-03-16 21:30:52 -0800	452		\$PEDATA, P1016.03, T25.54, H61.05, GFL0.00, GFH0.00, C293.08, TC0.00, *3686
1142574052616	2006-03-16 21:40:52 -0800	453		\$PEDATA, P1016.09, T25.66, H60.85, GFL0.00, GFH0.00, C294.85, TC0.00, *3708
1142574654961	2006-03-16 21:50:54 -0800	454		\$PEDATA, P1014.85, T25.29, H61.21, GFL0.00, GFH0.00, C290.50, TC0.00, *3688
1142575252617	2006-03-16 22:00:52 -0800	455		\$PEDATA, P1013.00, T25.82, H60.34, GFL0.14, GFH0.13, C292.11, TC0.00, *3684
1142575852616	2006-03-16 22:10:52 -0800	456		\$PEDATA, P1016.28, T25.86, H60.19, GFL0.00, GFH-0.13, C292.28, TC0.00, *3752
1142576452617	2006-03-16 22:20:52 -0800	457		\$PEDATA, P1017.14, T25.60, H60.53, GFL0.00, GFH0.13, C295.18, TC0.00, *3695
1142577052647	2006-03-16 22:30:52 -0800	458		\$PEDATA, P1013.96, T25.66, H60.44, GFL0.00, GFH-0.13, C293.73, TC0.00, *3751
1142577652627	2006-03-16 22:40:52 -0800	459		\$PEDATA, P1016.11, T25.73, H60.33, GFL0.00, GFH0.00, C293.73, TC0.00, *3688
1142578253117	2006-03-16 22:50:53 -0800	460		\$PEDATA, P1013.97, T25.69, H60.35, GFL0.14, GFH-0.13, C290.50, TC0.00, *3752
1142578852621	2006-03-16 23:00:52 -0800	461		\$PEDATA, P1016.04, T25.57, H60.49, GFL0.00, GFH0.00, C293.73, TC0.00, *3699
1142579452669	2006-03-16 23:10:52 -0800	462		\$PEDATA, P1015.95, T25.42, H60.60, GFL0.00, GFH-0.13, C291.47, TC0.00, *3743
1142580052664	2006-03-16 23:20:52 -0800	463		\$PEDATA, P1015.82, T25.15, H61.06, GFL0.00, GFH0.00, C294.37, TC0.00, *3693
1142580652664	2006-03-16 23:30:52 -0800	464		\$PEDATA, P1015.76, T25.05, H61.24, GFL0.00, GFH-0.13, C291.79, TC0.00, *3747
1142581252616	2006-03-16 23:40:52 -0800	465		\$PEDATA, P1015.79, T25.14, H61.06, GFL0.00, GFH0.00, C290.66, TC0.00, *3696
1142581852621	2006-03-16 23:50:52 -0800	466		\$PEDATA, P1018.85, T24.93, H61.62, GFL0.00, GFH0.00, C293.40, TC0.00, *3699
1142582459071	2006-03-17 00:00:59 -0800	467		\$PEDATA, P1016.66, T24.85, H61.71, GFL0.00, GFH-0.38, C290.34, TC0.00, *3753
1142583052917	2006-03-17 00:10:52 -0800	468		\$PEDATA, P1015.63, T24.81, H61.83, GFL0.00, GFH0.00, C290.50, TC0.00, *3690
1142583652616	2006-03-17 00:20:52 -0800	469		\$PEDATA, P1017.72, T24.85, H61.77, GFL0.00, GFH0.13, C290.18, TC0.00, *3707
1142584252616	2006-03-17 00:30:52 -0800	470		\$PEDATA, P1015.56, T24.71, H61.94, GFL0.00, GFH-0.13, C289.21, TC0.00, *3748
1142584852656	2006-03-17 00:40:52 -0800	471		\$PEDATA, P1015.52, T24.72, H61.94, GFL0.00, GFH0.00, C291.15, TC0.00, *3692
1142585459186	2006-03-17 00:50:59 -0800	472		\$PEDATA, P1015.39, T24.47, H62.46, GFL0.00, GFH0.00, C290.18, TC0.00, *3699
1142586052616	2006-03-17 01:00:52 -0800	473		\$PEDATA, P1015.35, T24.32, H62.72, GFL0.00, GFH0.13, C290.83, TC0.00, *3694
1142586652616	2006-03-17 01:10:52 -0800	474		\$PEDATA, P1016.40, T24.39, H62.64, GFL0.00, GFH0.00, C288.57, TC0.00, *3703
1142587252617	2006-03-17 01:20:52 -0800	475		\$PEDATA, P1016.43, T24.44, H62.55, GFL0.00, GFH-0.13, C291.63, TC0.00, *3742
1142587852616	2006-03-17 01:30:52 -0800	476		\$PEDATA, P1015.30, T24.26, H62.81, GFL0.00, GFH-0.13, C289.86, TC0.00, *3748
1142588452621	2006-03-17 01:40:52 -0800	477		\$PEDATA, P1015.24, T24.17, H62.89, GFL0.00, GFH-0.13, C289.86, TC0.00, *3759
1142589052628	2006-03-17 01:50:52 -0800	478		\$PEDATA, P1017.35, T24.18, H63.10, GFL0.00, GFH0.13, C290.50, TC0.00, *3687
1142589652709	2006-03-17 02:00:52 -0800	479		\$PEDATA, P1014.24, T24.35, H62.73, GFL0.00, GFH0.00, C290.50, TC0.00, *3685
1142590252691	2006-03-17 02:10:52 -0800	480		\$PEDATA, P1015.33, T24.34, H62.73, GFL0.00, GFH0.00, C292.60, TC0.00, *3688
1142590862181	2006-03-17 02:21:02 -0800	481		\$PEDATA, P1014.00, T23.92, H63.56, GFL0.00, GFH0.13, C288.09, TC0.00, *3698
1142591452616	2006-03-17 02:30:52 -0800	482		\$PEDATA, P1015.10, T24.01, H63.42, GFL0.00, GFH0.00, C290.18, TC0.00, *3675
1142592052616	2006-03-17 02:40:52 -0800	483		\$PEDATA, P1015.16, T24.05, H63.40, GFL0.14, GFH0.00, C288.73, TC0.00, *3696
1142592652674	2006-03-17 02:50:52 -0800	484		\$PEDATA, P1014.00, T23.79, H63.85, GFL0.00, GFH-0.13, C292.44, TC0.00, *3744
1142593258111	2006-03-17 03:00:58 -0800	485		\$PEDATA, P1015.07, T23.92, H63.56, GFL0.00, GFH0.00, C290.18, TC0.00, *3695
1142593852615	2006-03-17 03:10:52 -0800	486		\$PEDATA, P1015.05, T23.87, H63.59, GFL0.00, GFH0.00, C290.83, TC0.00, *3702
1142594452619	2006-03-17 03:20:52 -0800	487		\$PEDATA, P1014.87, T23.43, H64.36, GFL0.00, GFH0.00, C290.02, TC0.00, *3690
1142595052636	2006-03-17 03:30:52 -0800	488		\$PEDATA, P1014.90, T23.59, H64.20, GFL0.00, GFH0.00, C289.86, TC0.00, *3704
1142595652626	2006-03-17 03:40:52 -0800	489		\$PEDATA, P1013.96, T23.81, H63.86, GFL0.00, GFH0.13, C288.73, TC0.00, *3714
1142596254730	2006-03-17 03:50:54 -0800	490		\$PEDATA, P1014.86, T23.52, H64.28, GFL0.00, GFH0.00, C289.86, TC0.00, *3710
1142596852615	2006-03-17 04:00:52 -0800	491		\$PEDATA, P1014.79, T23.45, H64.17, GFL0.00, GFH-0.13, C291.15, TC0.00, *3746
1142597458302	2006-03-17 04:10:58 -0800	492		\$PEDATA, P1013.70, T23.34, H64.31, GFL-0.14, GFH-0.25, C288.57, TC0.00, *3795

1142598052664	2006-03-17 04:20:52 -0800	493	\$PEDATA, P1012.67, T23.41, H64.14, GFL0.00, GFH0.00, C287.44, TC0.00, *3692
1142598652615	2006-03-17 04:30:52 -0800	494	\$PEDATA, P1014.83, T23.50, H63.97, GFL0.00, GFH0.00, C290.34, TC0.00, *3695
1142599252684	2006-03-17 04:40:52 -0800	495	\$PEDATA, P1012.57, T23.24, H64.33, GFL0.00, GFH0.00, C290.02, TC0.00, *3681
1142599852616	2006-03-17 04:50:52 -0800	496	\$PEDATA, P1014.55, T22.97, H64.84, GFL0.00, GFH0.00, C289.54, TC0.00, *3711
1142600452665	2006-03-17 05:00:52 -0800	497	\$PEDATA, P1013.66, T23.34, H64.13, GFL0.00, GFH-0.13, C290.83, TC0.00, *3739
1142601057951	2006-03-17 05:10:57 -0800	498	\$PEDATA, P1014.76, T23.42, H63.99, GFL0.00, GFH0.13, C287.12, TC0.00, *3706
1142601652626	2006-03-17 05:20:52 -0800	499	\$PEDATA, P1014.71, T23.21, H64.23, GFL0.00, GFH0.00, C290.99, TC0.00, *3691
1142602261551	2006-03-17 05:31:01 -0800	500	\$PEDATA, P1014.63, T23.20, H64.23, GFL0.00, GFH0.00, C286.64, TC0.00, *3688
1142602852616	2006-03-17 05:40:52 -0800	501	\$PEDATA, P1014.15, T24.26, H62.59, GFL0.00, GFH0.13, C293.73, TC0.00, *3701
1142603457811	2006-03-17 05:50:57 -0800	502	\$PEDATA, P1015.31, T24.42, H62.71, GFL0.00, GFH0.00, C290.34, TC0.00, *3682
1142604052617	2006-03-17 06:00:52 -0800	503	\$PEDATA, P1013.60, T25.08, H61.77, GFL-0.14, GFH0.00, C292.92, TC0.00, *3746
1142604652621	2006-03-17 06:10:52 -0800	504	\$PEDATA, P1015.88, T25.23, H61.95, GFL0.00, GFH0.25, C293.89, TC0.00, *3719
1142605252616	2006-03-17 06:20:52 -0800	505	\$PEDATA, P1015.33, T24.34, H63.28, GFL0.00, GFH0.00, C288.57, TC0.00, *3700
1142605852621	2006-03-17 06:30:52 -0800	506	\$PEDATA, P1015.23, T24.14, H63.38, GFL0.00, GFH0.13, C290.66, TC0.00, *3695
1142606452621	2006-03-17 06:40:52 -0800	507	\$PEDATA, P1015.56, T24.81, H62.14, GFL0.00, GFH0.13, C292.11, TC0.00, *3690
1142607057471	2006-03-17 06:50:57 -0800	508	\$PEDATA, P1014.42, T24.61, H62.61, GFL0.00, GFH-0.13, C290.66, TC0.00, *3737
1142607657482	2006-03-17 07:00:57 -0800	509	\$PEDATA, P1016.31, T24.20, H63.33, GFL-0.14, GFH0.13, C292.11, TC0.00, *3729
1142608252616	2006-03-17 07:10:52 -0800	510	\$PEDATA, P1016.33, T24.26, H62.90, GFL0.00, GFH0.00, C288.25, TC0.00, *3695
1142608852666	2006-03-17 07:20:52 -0800	511	\$PEDATA, P1015.26, T24.30, H62.78, GFL0.00, GFH0.13, C292.44, TC0.00, *3697
1142609452621	2006-03-17 07:30:52 -0800	512	\$PEDATA, P1018.70, T24.67, H62.55, GFL0.14, GFH0.00, C291.31, TC0.00, *3700
1142610052616	2006-03-17 07:40:52 -0800	513	\$PEDATA, P1015.41, T24.50, H62.78, GFL0.00, GFH0.00, C292.60, TC0.00, *3690
1142610657461	2006-03-17 07:50:57 -0800	514	\$PEDATA, P1016.22, T24.06, H63.58, GFL0.00, GFH-0.13, C291.79, TC0.00, *3748
1142611253500	2006-03-17 08:00:53 -0800	515	\$PEDATA, P1015.19, T24.20, H63.33, GFL0.00, GFH-0.13, C289.86, TC0.00, *3747
1142611852616	2006-03-17 08:10:52 -0800	516	\$PEDATA, P1015.48, T24.67, H62.68, GFL0.00, GFH0.13, C294.85, TC0.00, *3717
1142612452701	2006-03-17 08:20:52 -0800	517	\$PEDATA, P1014.20, T24.17, H63.63, GFL0.00, GFH0.00, C291.47, TC0.00, *3688
1142613057842	2006-03-17 08:30:57 -0800	518	\$PEDATA, P1017.62, T24.69, H62.68, GFL0.00, GFH-0.13, C293.89, TC0.00, *3765
1142613652967	2006-03-17 08:40:52 -0800	519	\$PEDATA, P1016.36, T24.31, H63.37, GFL0.14, GFH0.13, C290.83, TC0.00, *3702








Chart was not created because line would be flat with value of 0.0

