

Planetary Gearheads 12/4

Gearhead Series	Reduction ratio	Number of gear stages	3D - File Name
12/4 (with sintered bearings on output shaft)	4:1	1	12_4 1stages.stp
	16:1	2	12_4 2stages.stp
	64:1	3	12_4 3stages.stp
	256:1	4	12_4 4stages.stp
	1024:1	5	12_4 5stages.stp
12/4K (with ball bearings on output shaft)	4:1	1	12_4K 1stages.stp
	16:1	2	12_4K 2stages.stp
	64:1	3	12_4K 3stages.stp
	256:1	4	12_4K 4stages.stp
	1024:1	5	12_4K 5stages.stp

Conditions of Use

The FAULHABER CAD 3D-Drawings are a free service of FAULHABER MINIMOTOR SA, 6980 Croglio, Switzerland. They may only be used and distributed in a complete and unaltered form. All copy rights reserved.

Please Note: All dimensions are displayed using the metric system (millimeters). Your CAD system maybe preset to another system of measurements or dimenstions. Preset millimeter in the CAD application before importing the file!

These models are intended as a conceptual aid only. All dimensions are subject to change without notice. The most up-to-date drawings can be downloaded from the Internet at:

Though we endeavor to maintain the accuracy of the models provided we can provide no guarantee of their accuracy. Use of the models is at your own risk.

With the use of the data you agree with the aforementioned conditions.