

**MONTEREY
BAY
AQUARIUM
RESEARCH
INSTITUTE**



PURCHASE ORDER

Purchase Order Invalid Without PO#

PO#: 1611185

Date: 10/19/2016

VENDOR

McLane Research Laboratories, Inc.
Falmouth Technology Park
121 Bernard Saint Jean Drive
East Falmouth, MA 02536 USA

Phone:

Fax:

Email:

Contact:

Payment Terms: NET 30

Customer Number:

SHIPPING

Ship To:

MBARI Building A
7700 Sandholdt Road
Moss Landing, CA 95039-9644 USA

Ship Via: Best Way

Expected Delivery Date: 11/2/2016

FOB: Shipping Point

MBARI CONTACT

Name: Huffard, Christine

Phone:

Fax:

Email: chuffard@mbari.org

SEND INVOICES TO

MBARI Accounts Payable
7700 Sandholdt Rd.
Moss Landing, CA 95039-9644
Phone: (831) 775-1700 Fax: (831) 775-1630

PROJECT

Project	Account	RefNum	Amount
901618.00	5360-000		\$1,130.00

REMARKS

ITEM DETAIL

#	Description	Part #	Quantity	U/M	Unit Cost	Ext Amount
1	Spares: Bridles, Powder-coated hardware, Nylon rope [all Traps]	TRAPBridleNP	2.0000	Each	\$565.00	\$1,130.00

Shipping Cost: \$75.00

Sales/Use Tax: \$86.22

Purchase Order Amount: \$1,291.22

ATTACHMENTS

Description	FileName	Action
quote	2016-AS-184_V1.pdf	Download

that all contractors and subcontractors having 50 or more employees and a federal government contract or subcontract of \$50,000 or more must develop a written affirmative action plan under the federal guidelines.

Export Compliance The vendor (or supplier) agrees that it will provide the export control classification associated with the commodity being purchased, to the extent that this item is controlled either under the Export Administration Regulations (EAR) or the International Traffic in Arms Regulations (ITAR). For EAR-controlled items, the correct Export Control Classification Number (ECCN) classification based on the Commerce Control List will be provided. For ITAR items, the correct U.S. Munitions List (USML) category will be provided. In both cases, to the extent that the item includes technical data such as operational manuals, such data must also be classified. In the event that the vendor (or supplier) is unable to comply with this instruction, it will notify MBARI within ten days of purchase order, indicating the reason for non-compliance and recommended solution.