



REPORT OF A THOROUGH EXAMINATION OF LIFTING EQUIPMENT
In accordance with Lifting Operations and Lifting Equipment Regulations 1998

Date of Thorough Examination	Date of Report	Customer Order Number	Job Number	Report Number
16/01/2008	16/01/2008	60930	LRJ/5274	LRT07863
Customer Name & Address		Address at which examination was made		
SOIL MACHINE DYNAMICS TURBINIA WORKS DAVEY BANK WALLSEND TYNE AND WEAR		LIFT-RITE ENGINEERING SERVICES LTD MORSTON HOUSE MORTON QUAY STEPHENSON STREET WALLSEND TYNE & WEAR NE28 6UQ		

Qty	ID Number	Description of Equipment	Working Load Limit
1	AB 6985	TEST 1 MBARI LIFT POINT DRAWING AB5465 (ITEM 20 AB6985)	-
	AB 5477	TEST 2 MBARI LIFT POINT DRAWING AB5465 (ITEM 40 AB5477)	

Where the thorough examination included testing, Particulars of any test:

PROOF LOAD APPLIED : TEST 1 - 18 TONNE HELD FOR 1 MINUTE
TEST 2 - 18 TONNE HELD FOR 1 MINUTE

Date of first issue for use.	N/A
Date of last thorough examination	16/01/2008
The latest date by which the next thorough examination must be carried out	16/01/2009
Is this the first examination after installation, after assembly at the new site or location ?	N/A
If YES, has the equipment been installed correctly ?	N/A
If NO, has the examination been carried out:	
a) Within an interval of 6 months under regulation 9(3)(a)(i)	
b) Within an interval of 12 months under regulation 9(3)(a)(ii)	
c) In accordance with an examination scheme under regulation 9(3)(a)(iii)	
d) After the occurrence of exceptional circumstances under regulation 9(3)(a)(iv)	YES
Identification of any part found to have defect which is or could become a danger to persons and a description of the defect	N/A
Is the above defect of immediate danger to persons ?	N/A
Is the above defect not yet, but could become a danger to persons ?	N/A
If YES, Time by which it could become a danger.	N/A
Particulars of any repair, renewal or alteration required to remedy the defect identified.	N/A
Is the equipment safe to operate ?	YES

Name of person making this report: JOHN WELSH

Name of person signing this report: GLYN GEACH

Signature:

Date: 16/01/2008