



TELEDYNE BENTHOS
Undersea Instrument Systems
 A Teledyne Technologies Company
www.Benthos.com



TELEDYNE TAPTONE
Package Inspection Systems
 A Teledyne Technologies Company
www.TapTone.com

49 Edgerton Drive • North Falmouth, MA 02556 USA • T: +1 508.563.1000 • F: +1 508.564.9945

RMA Estimate: 10795
Sales Order: CO 10795
Date: 1/29/09

To:

Alana Sherman
 or Alana Sherman

Phone #: (831) 775-1780
 Fax #: (831) 775-1646

MBARI ACCOUNTS PAYABLE

Email: alana@mbari.org

Equipment / Proposed Work

D-855-86

ASSY, TOP XT-6001 10" MKS

S/N

68511

Eval / Repair Est Delivery ARO

600.00 ASAP

Problem found:

The customer requested the receive frequency and the transmit be change to RX=9.0 khz & TX=11.0khz. Also replace the battery.

Proposed

Retune the PC board pair and replace the battery. Perform a operational test.

ESTIMATED TOTAL

600.00

The value of this repair has been estimated to the best of our ability on the basis of the reported symptoms and in-house observation. If during the course of repair it becomes apparent that additional costs will be incurred, you will be notified of the increase for approval before proceeding.

If you wish to proceed with the repair, please provide either a purchase order or credit card number. Any questions, feel free to contact the Teledyne Benthos Repair Center Administrator at 1.508.563.1582. PO should be faxed to 1.508.564.9945. Thank you!