

**MONTEREY
BAY
AQUARIUM
RESEARCH
INSTITUTE**



PURCHASE ORDER

Purchase Order Invalid Without PO#

PO#: 1910593

Date: 5/7/2019

VENDOR

Hydraulic Controls, Inc.
PO Box 8157
Emeryville, CA 94662
USA

Phone: (510) 658-8300

Fax: (209) 466-3309

Email:

prodriguez@hydraulic-
controls.com

Contact: Pam Rodriguez

Payment Terms: .5% 10 N
30

Customer Number: 409250

SHIPPING

Ship To:

MBARI Building A
7700 Sandholdt Road
Moss Landing, CA 95039-9644 USA

Ship Via: Best Way

Expected Delivery Date: 5/24/2019

FOB: Shipping Point

MBARI CONTACT

Name: Hamilton, Andy

Phone: (831) 775-1861

Fax: (831) 775-1646

Email: hamilton@mbari.org

SEND INVOICES TO

MBARI Accounts Payable

7700 Sandholdt Rd.

Moss Landing, CA 95039-9644

Phone: (831) 775-1700 Fax: (831) 775-1630

Email: accountspayable@mbari.org

PROJECT

Project	Account	RefNum	Amount
901101.10	1500-568		\$238.64

REMARKS

Thank you! Please ship Sun Valve from stock immediately and follow up with Bucher valve when available. i.e. Don't wait to complete the order.

ITEM DETAIL

#	Description	Part #	Quantity	U/M	Unit Cost	Ext Amount
1	Pilot Operated reducing/relieving valve - T163A	PPBBLAN	2.0000	Each	\$72.38	\$144.76
2	Bucher Relief Valve	RVBD-08-N-S-0-30	2.0000	Each	\$46.94	\$93.88

Shipping Cost: \$60.00

Sales/Use Tax: \$18.49

Purchase Order Amount: \$317.13



MBARI is an Affirmative Action/Equal Opportunity employer. MBARI does not discriminate against any employee or applicant for employment because of race, color, sex, or national origin. MBARI will comply with the provisions of Executive Order 11246 of 9/24/65, and relevant rules and regulations as required by law. Please be advised that all contractors and subcontractors having 50 or more employees and a federal government contract or subcontract of \$50,000 or more must develop a written affirmative action plan under the federal guidelines.

Export Compliance The vendor (or supplier) agrees that it will provide the export control classification associated with the commodity being purchased, to the extent that this item is controlled either under the Export Administration Regulations (EAR) or the International Traffic in Arms Regulations (ITAR). For EAR-controlled items, the correct Export Control Classification Number (ECCN) classification based on the Commerce Control List will be provided. For ITAR items, the correct U.S. Munitions List (USML) category will be provided. In both cases, to the extent that the item includes technical data such as operational manuals, such data must also be classified. In the event that the vendor (or supplier) is unable to comply with this instruction, it will notify MBARI within ten days of purchase order, indicating the reason for non-compliance and recommended solution.