

**MONTEREY
BAY
AQUARIUM
RESEARCH
INSTITUTE**



PURCHASE ORDER

Purchase Order Invalid Without PO#

PO#: 1710239

Date: 2/6/2017

VENDOR

Teledyne Benthos
49 Edgerton Drive
North Falmouth, MA 02556-2826 USA
Phone: (508) 563-1000
Fax: (508) 563-6444
Email: joseph.borden@teledyne.com
Contact: Joe Borden
Payment Terms: NET 30
Customer Number: OMBARI

SHIPPING

Ship To:
MBARI Building A
7700 Sandholdt Road
Moss Landing, CA 95039-9644 USA
Ship Via: Fed Ex
Expected Delivery Date: 2/21/2017
FOB: Shipping Point

MBARI CONTACT

Name: Chaffey, Mark
Phone: (831) 775-1708
Fax: (831) 775-1646
Email: chma@mbari.org

SEND INVOICES TO

MBARI Accounts Payable
7700 Sandholdt Rd.
Moss Landing, CA 95039-9644
Phone: (831) 775-1700 Fax: (831) 775-1630

PROJECT

Project	Account	RefNum	Amount
901411.00	5360-000		\$3,450.00

REMARKS

As per T.B. quote 7030 dated 2/2/2017. Expedited delivery is requested. Expected delivery is 2 weeks ARO. Note that this unit replaces C-250-378 transducer serial number 71049 which is being returned for credit on separate RMA #35315. Use FedEx 2day service, customer account #1543-1653-1

ITEM DETAIL

#	Description	Part #	Quantity	U/M	Unit Cost	Ext Amount
1	LF directional transducer assembly, "dual block" configuration, HYDRO, AT-12A1 W/BLK SS	D-270-9-7	1.0000	Each	\$3,450.00	\$3,450.00

Shipping Cost: \$100.00

Sales/Use Tax: \$254.61

Purchase Order Amount: \$3,804.61

MBARI is an Affirmative Action/Equal Opportunity employer. MBARI does not discriminate against any employee or applicant for employment because of race, color, sex, or national origin. MBARI will comply with the provisions of Executive Order 11246 of 9/24/65, and relevant rules and regulations as required by law. Please be advised that all contractors and subcontractors having 50 or more employees and a federal government contract or subcontract of \$50,000 or more must develop a written affirmative action plan under the federal guidelines.

Export Compliance The vendor (or supplier) agrees that it will provide the export control classification associated with the commodity being purchased, to the extent that this item is controlled either under the Export Administration Regulations (EAR) or the International Traffic in Arms Regulations (ITAR). For EAR-controlled items, the correct Export

Control Classification Number (ECCN) classification based on the Commerce Control List will be provided. For ITAR items, the correct U.S. Munitions List (USML) category will be provided. In both cases, to the extent that the item includes technical data such as operational manuals, such data must also be classified. In the event that the vendor (or supplier) is unable to comply with this instruction, it will notify MBARI within ten days of purchase order, indicating the reason for non-compliance and recommended solution.