








plot config files

plotting is handled by three scripts:

qsee: manages data extraction and plot creation
xpres: generates CSV data from archive
plot: generates plot using GNU plotutils

env-qc

env-qc contains environment definitions used by qsee and qplot. The config files for qsee and qplot may override these variables

gw-id.conf

xpres and qsee config files reference insrtument IDs
IDs, streams and label mappings are defined in gw-id.conf

data extraction rules

xp-data.conf

xp-jit.conf

data extraction and plotting divided into multiple qsee jobs, so that they may be run in parallel and/or at different times

qsee job def

qs-sci-1.conf

qs-sci-2.conf

qs-sys-1.conf

qs-sys-2.conf

qs-met.conf

plot jobs defined in configuration files

qplot job def

qp-sci-1.conf


qp-sci-2.conf

qp-sys-1.conf

qp-sys-2.conf

qp-met.conf

plot manifest



plot

conf

notes