

POLYHEDRON LABS Lab #34612

Sample : SURFACE DOWN

Run # : 1


Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :

- L - draw lines
- R - current result
- C - change labels
- P - print graph
- Q - quit



POLYHEDRON LABS Lab #34612

Sample : SURFACE DOWN

Run # : 2


Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :

- L - draw lines
- R - current result
- C - change labels
- P - print graph
- Q - quit



POLYHEDRON LABS Lab #34612

Sample : SURFACE DOWN

Run # : 3


Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :

- L - draw lines
- R - current result
- C - change labels
- P - print graph
- Q - quit



POLYHEDRON LABS Lab #34612

Sample : SURFACE DOWN

Run # : 4

Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :


L - draw lines

R - current result

C - change labels

P - print graph

Q - quit



POLYHEDRON LABS Lab #34612

Sample : SURFACE DOWN


Run # : 5

Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :
L - draw lines
R - current result
C - change labels
P - print graph
Q - quit



POLYHEDRON LABS Lab #34612

Sample : SIGN ON THE SIDE

Run # : 6


Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :

- L - draw lines
- R - current result
- C - change labels
- P - print graph
- Q - quit



POLYHEDRON LABS Lab #34612

Sample : SIGN ON THE SIDE

Run # : 7


Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :

- L - draw lines
- R - current result
- C - change labels
- P - print graph
- Q - quit



POLYHEDRON LABS Lab #34612

Sample : SIGN ON THE SIDE

Run # : 8


Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :

- L - draw lines
- R - current result
- C - change labels
- P - print graph
- Q - quit



POLYHEDRON LABS Lab #34612

Sample : SIGN ON THE SIDE

Run # : 9


Range : 5

COMPRESSIVE TESTING

Speed in/min: 0.05

Select :

- L - draw lines
- R - current result
- C - change labels
- P - print graph
- Q - quit



POLYHEDRON LABS Lab #34612

Sample : SIGN ON THE SIDE
Run # : 10
Range : 5

COMPRESSIVE TESTING
Speed in/min: 0.05

Select :
L - draw lines
R - current result
C - change labels
P - print graph
Q - quit

