



Ad Serter SDI Recorder Working Instruction of Auto Transcoder September 5th, 2018

For sales information and technical support contact:



11409 West Bernardo Court
San Diego, CA, USA 92127
Phone: (858) 613-1818
Fax: (858) 613-1815
support@dveo.com

© 2018 Computer Modules, Inc. DVEO and Ad Serter are trademarks of Computer Modules, Inc. All other trademarks and registered trademarks are the properties of their respective owners. All rights reserved. Specifications are subject to change without notice.

Steps to follow while working with AutoTranscoder.

Ad Serter records file in .ts format with ,mp4 extesion.

To convert these files, into required .mp4 format, A file transcoder utility is provided.

1. If the files are getting recorded then click on Stop All recording option from Web UI.
2. Click on the file name "Start AutoTranscoder.bat" available on Desktop. (This will start to Transcode the files)
3. To view the transcoded file follow the path "D:\Recording\AdSerter1\1920_1080_1" for 1st Recorder, "D:\Recording\AdSerter1\1920_1080_2" for 2nd recorder and so on...
4. To Stop the Auto Transcoder click on "Stop AutoTranscoder.bat" on Desktop.

NOTE: Always Stop recording before using Start Auto transcoder else the file will not be transcoded completely.

Autotranscoder transcodes files into required .mp4 format as soon as the file is available in "Watch folder". Currently, all Recording folders are set as Watch folders.