

**MONTEREY
BAY
AQUARIUM
RESEARCH
INSTITUTE**



PURCHASE ORDER

Purchase Order Invalid Without PO#

PO#: 1610683

Date: 5/26/2016

VENDOR

Bender Inc.
700 Fox Chase
Highlands Corp Center
Coatesville, PA 19320 USA
Phone: (800) 356-4266
Fax: (610) 383-7100
Email:
Contact: KAREN
Payment Terms: NET 30
Customer Number:

SHIPPING

Ship To:
MBARI Building A
7700 Sandholdt Road
Moss Landing, CA 95039-9644 USA

Ship Via: Best Way
Expected Delivery Date: 6/21/2016
FOB: Shipping Point

MBARI CONTACT

Name: Chad Keczy
Phone: (831) 775-2039
Fax: (831) 775-1646
Email: ckecy@mbari.org

SEND INVOICES TO

MBARI Accounts Payable
7700 Sandholdt Rd.
Moss Landing, CA 95039-9644
Phone: (831) 775-1700 Fax: (831) 775-1630

PROJECT

Project	Account	RefNum	Amount
901007.00	5330-000		\$1,965.00

REMARKS

ITEM DETAIL

#	Description	Part #	Quantity	U/M	Unit Cost	Ext Amount
1	iso685 Ungrounded AC Ground Fault Monitor	B91067010	1.0000	Each	\$1,965.00	\$1,965.00

Shipping Cost: \$25.00

Sales/Use Tax: \$149.93

Purchase Order Amount: \$2,139.93

ATTACHMENTS

Description	FileName	Action
Quote	TC_Monterey Bay_iso685_050416_V1.pdf	Download

MBARI is an Affirmative Action/Equal Opportunity employer. MBARI does not discriminate against any employee or applicant for employment because of race, color, sex, or national origin. MBARI will comply with the provisions of Executive Order 11246 of 9/24/65, and relevant rules and regulations as required by law. Please be advised that all contractors and subcontractors having 50 or more employees and a federal government contract or subcontract of \$50,000 or more must develop a written affirmative action plan under the federal guidelines.

Export Compliance The vendor (or supplier) agrees that it will provide the export control classification associated with the commodity being purchased, to the extent that this item is controlled either under the Export Administration

Regulations (EAR) or the International Traffic in Arms Regulations (ITAR). For EAR-controlled items, the correct Export Control Classification Number (ECCN) classification based on the Commerce Control List will be provided. For ITAR items, the correct U.S. Munitions List (USML) category will be provided. In both cases, to the extent that the item includes technical data such as operational manuals, such data must also be classified. In the event that the vendor (or supplier) is unable to comply with this instruction, it will notify MBARI within ten days of purchase order, indicating the reason for non-compliance and recommended solution.