


Assembly Instructions

Assemble valve assembly using four (4) M3 screws



Assembly will sit flush with indicated surface and threaded holes

