

200109 - Core Mooring Data

Week 41

1. Mike McCann
 - a. Tracked down a bad depth value for M1's SWR instrument

Week 38

1. Mike McCann
 - a. Copied recovered M1 deployment data to OceanSITES folder - as is done following a mooring turn

Week 36

1. Mike McCann
 - a. Submitted Phase 2 response

Week 29

1. Mike McCann
 - a. Submitted proposal for 2021

Week 11

1. Mike McCann
 - a. Fixed the way Salinity is calculated for deep microcats without pressure sensors – simply use nominal depth as a standin for pressure, which is better than using 0 for pressure

Week 8

1. Mike McCann
 - a. Needed to regenerate the hourlyM1.nc file because the file from the last microcat deployment had some issues – Fred quickly repaired it and now John is able to use it