



19700 Janelia Farm Boulevard, Ashburn, VA 20147
 Phone 703-726-5500 • Fax 703-726-5600
www.comsearch.com

User: Dong Shin
PDF's: MTTORO
Job Number: 140624COMSDS03
Date/Time: June 24, 2014 3:40 PM

Path Warnings Document

*This document provides important information regarding FCC restrictions that may apply to the system you are planning. **This list is intended as an informational guideline and is not guaranteed to encompass all possible licensing issues that may arise.** In some instances the restrictions are minor, but in other instances there may be a significant impact upon your system implementation. Comsearch recommends that you review this document carefully and consult with your Comsearch Engineering contact if you have any questions or concerns.*

1) MT TORO – S & E BLDG

18.0 GHz

Monterey Bay Aquarium Research Inst

FCC Rule Part(s)	Description	Result / Action
N/A	Path length exceeds the maximum range for the band selected.	Verify Coordinates
N/A	MT TORO AMSL does not match AMSL on MT TORO – S & E BLDG.	Verify Ground Elevation
N/A	S & E BLDG AMSL does not match AMSL on MT TORO – S & E BLDG.	Verify Ground Elevation
N/A	MT TORO using older revision of antenna. No action needed unless antenna is brand new.	Verify if antenna is new

2) MT TORO – S & E BLDG

18.0 GHz

Monterey Bay Aquarium Research Inst

FCC Rule Part(s)	Description	Result / Action
N/A	Path length exceeds the maximum range for the band selected.	Verify Coordinates

N/A	MT TORO AMSL does not match AMSL on MT TORO – S & E BLDG.	Verify Ground Elevation
N/A	S & E BLDG AMSL does not match AMSL on MT TORO – S & E BLDG.	Verify Ground Elevation
N/A	MT TORO using older revision of antenna. No action needed unless antenna is brand new.	Verify if antenna is new