



New Features

- None

Improvements

- Ad Hoc connection and transmission stability improvements

Changes

- None

Bug Fixes

- Fixed PAL (576i) SD-SDI output