

**DC Drive
Assembly Notes
MBARI 5580ASY-1.00**



Revision Date 04/29/98 1:33 PM

For PCB rev 1.00, Schematic rev 1.2:

Before mounting U1, modify the traces to pins 3 and 4 to reverse them such that the trace that led to pin 3 now goes to pin 4, and the trace that went to pin 4 now goes to pin 3.

Consult the configuration sheet to determine correct part values to load.

Consult configuration sheet for type and orientation (topside, bottomside) of connectors.

C7 has been changed to a ceramic type, and is physically smaller than the component it replaces.

Do not install C15 and C16.

Consult configuration sheet for jumper positions.

END