

HOBİ Labs, Inc.

Instrument Service Document

Instrument: HydroScat-2

Serial Number: H2010336

Institution: MBARI

Contact: Jared Fiqurski

RMA#: H23612A

Service Performed:

Incoming inspection and test	
------------------------------	--

Replace zinc anodes

Replace copper face plate

Optional calibration before service

Standard calibration after service

Parts replaced or installed:[illegible]**Comments:**

Date Completed: 2/11/13

Lead Technician: DRD