



HOBILabs, Inc.

Instrument Service Document

Instrument: HydroScat-2
Serial Number: H2070752
Institution: MBARI
Contact: Paul Coenen
RMA#: HS208295F

Service Performed:

Incoming inspection and test

Full calibration

Outgoing inspection and tet

Parts replaced or installed:

Qty	P/N	Description
	---NONE---	

Comments:

The zinc anodes on the instrument must be replaced. The customer opted to do this himself.

Date Completed: 2/2/09

Lead Technician: CE