



---

## Radiometer Service Report

**Date:** 10/18/2023 **SR #:** 1005519551 **Sensor Type:** HyperOCRR08W

**S/N:** 254 **Customer:** MBARI - MONTEREY BAY AQUARIUM  
RESEARCH INSTITUTE

### Diagnosis:

- No Problems Found.

### Repairs and Modifications:

- Standard Service.
- Passed Calibration.
- The Calibrated output was within 5% of the reference sensor output under natural light conditions.