



Radiometer Service Report

Date 3/24/21 **SR #:** 1005511596 **Sensor Type:** HyperOCR ICSW

S/N 294 **Customer** MBARI

Diagnosis:

Failed Calibration. High Dark Range.

Repairs and Modifications:

Standard Service.

Did Post Calibration.

Cleaned the Optics to fix High Dark Range error.

Passed Calibration.

Calibrated output was within 5% of the reference sensor output under natural light conditions.