



---

## Radiometer Service Report

**Date** 9/29/21 **SR #:** 1005514012 **Sensor Type:** HyperOCR ICSW

**S/N** 295 **Customer** MBARI

### Diagnosis:

- No Problems Found.

### Repairs and Modifications:

- Standard Service.
- Passed Calibration.
- Calibrated output was within 5% of the reference sensor output under natural light conditions.