



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

68755

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 4/30/2012

Contact Jared Figurski

PO Number TBD

Serial Number 052340

Model Number SBE 05T

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

1. Pin 2 was found to be missing from the 2 pin connector.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Installed NEW two pin bulkhead connector(s).
3. Performed internal inspection and O-ring and thrust washer replacements.
4. Performed hydrostatic pressure test.

Special Notes:

SBE SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA



Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

68755

Customer Information:

Company	Monterey Bay Aquarium Research Institute	Date	4/30/2012
Contact	Jared Figurski		
PO Number	TBD		

Serial Number	052580
Model Number	SBE 05T

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

1. The pump head was found to be broken.
2. The end cap retainer was found to be cracked.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Installed NEW end cap retainer.
3. Installed NEW plastic pump head.
4. Performed internal inspection and O-ring and thrust washer replacements.
5. Performed hydrostatic pressure test.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

68755

Customer Information:

Company	Monterey Bay Aquarium Research Institute	Date	4/30/2012
----------------	--	-------------	-----------

Contact	Jared Figurski
----------------	----------------

PO Number	TBD
------------------	-----

Serial Number	055523
----------------------	--------

Model Number	SBE 05P
---------------------	---------

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

68755

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 4/30/2012

Contact Jared Figurski

PO Number TBD

Serial Number 16P57401-6520

Model Number SBE 16Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Attempt to recover any stored data.
3. Perform Routine Calibration Service.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Downloaded customers stored data.
3. Performed "Post Cruise" calibration of the temperature & conductivity sensors.
4. Calibrated the pressure sensor.
5. Performed complete system check and full diagnostic evaluation.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service

Report

RMA Number

68755

Customer Information:

Company Monterey Bay Aquarium Research Institute **Date** 4/30/2012

Contact Jared Figurski

PO Number TBD

Serial Number 431721

Model Number SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

Special Notes:

--