

SEA-BIRD ELECTRONICS, INC.

1808 136th Place N.E., Bellevue, Washington, 98005 USA
 Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0812
 CALIBRATION DATE: 09-Nov-06

SBE 37 TEMPERATURE CALIBRATION DATA
 ITS-90 TEMPERATURE SCALE

ITS-90 COEFFICIENTS

a0 = -2.400968e-004
 a1 = 3.304663e-004
 a2 = -6.298500e-006
 a3 = 2.541632e-007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	614935.1	1.0000	0.0000
4.5000	526855.0	4.5000	-0.0000
15.0000	337779.2	15.0000	0.0000
18.5000	293050.6	18.5000	-0.0000
23.9999	235808.0	23.9999	-0.0000
28.9999	194701.3	28.9999	0.0000
32.5000	170830.4	32.5000	-0.0000

Temperature ITS-90 = $1/[a_0 + a_1[\ln(n)] + a_2[\ln^2(n)] + a_3[\ln^3(n)]] - 273.15$ (°C)

Residual = instrument temperature - bath temperature

