

SEA-BIRD ELECTRONICS, INC.

13431 NE 20th Street, Bellevue, Washington, 98005-2010 USA

Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0818
CALIBRATION DATE: 02-Dec-10

SBE 37 CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -1.069559e+000
h = 1.549196e-001
i = -4.123071e-004
j = 5.743215e-005

CPcor = -9.5700e-008
CTcor = 3.2500e-006
WBOTC = -7.3731e-005

BATH TEMP (ITS-90)	BATH SAL (PSU)	BATH COND (Siemens/m)	INST FREQ (Hz)	INST COND (Siemens/m)	RESIDUAL (Siemens/m)
22.0000	0.0000	0.00000	2635.53	0.00000	0.00000
0.9999	34.6602	2.96388	5112.71	2.96384	-0.00004
4.4999	34.6398	3.26970	5303.13	3.26971	0.00001
15.0000	34.5962	4.24746	5870.20	4.24753	0.00007
18.5000	34.5863	4.59114	6056.75	4.59117	0.00004
24.0000	34.5754	5.14674	6346.54	5.14667	-0.00007
29.0000	34.5692	5.66638	6605.93	5.66631	-0.00008
32.5000	34.5656	6.03720	6784.92	6.03727	0.00007

$f = \text{INST FREQ} * \sqrt{1.0 + \text{WBOTC} * t} / 1000.0$

Conductivity = $(g + hf^2 + if^3 + jf^4) / (1 + \delta t + \epsilon p)$ Siemens/meter

t = temperature[°C]; p = pressure[decibars]; δ = CTcor; ϵ = CPcor;

Residual = instrument conductivity - bath conductivity

