

# SEA-BIRD ELECTRONICS, INC.

1808 136th Place N.E., Bellevue, Washington, 98005 USA  
 Phone: (425) 643 - 9866 Fax (425) 643 - 9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0828  
 CALIBRATION DATE: 31-May-07

SBE 37 TEMPERATURE CALIBRATION DATA  
 ITS-90 TEMPERATURE SCALE

## ITS-90 COEFFICIENTS

a0 = -3.034769e-005  
 a1 = 2.910942e-004  
 a2 = -3.506227e-006  
 a3 = 1.863931e-007

| BATH TEMP<br>(ITS-90) | INSTRUMENT<br>OUTPUT | INST TEMP<br>(ITS-90) | RESIDUAL<br>(ITS-90) |
|-----------------------|----------------------|-----------------------|----------------------|
| 1.0001                | 573771.0             | 1.0001                | -0.0000              |
| 4.5000                | 491174.1             | 4.5000                | 0.0000               |
| 15.0000               | 314104.1             | 14.9999               | -0.0001              |
| 18.5000               | 272273.1             | 18.5001               | 0.0001               |
| 24.0000               | 218784.6             | 24.0000               | -0.0000              |
| 29.0000               | 180410.3             | 29.0000               | 0.0000               |
| 32.5000               | 158144.6             | 32.5000               | -0.0000              |

Temperature ITS-90 =  $1/\{a_0 + a_1[\ln(n)] + a_2[\ln^2(n)] + a_3[\ln^3(n)]\} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

