



Sea-Bird Scientific
13431 NE 20th Street
Bellevue, WA 98005
USA

+1 425-643-9866
seabird@seabird.com
www.seabird.com

SENSOR SERIAL NUMBER: 1251
CALIBRATION DATE: 23-Dec-17

SBE 37 CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -1.031721e+000
h = 1.508830e-001
i = -7.360143e-005
j = 3.144735e-005

CPcor = -9.5700e-008
CTcor = 3.2500e-006
WBOTC = -2.8251e-005

BATH TEMP (° C)	BATH SAL (PSU)	BATH COND (S/m)	INSTRUMENT OUTPUT (Hz)	INSTRUMENT COND (S/m)	RESIDUAL (S/m)
22.0000	0.0000	0.00000	2615.55	0.00000	0.00000
1.0000	34.7778	2.97299	5144.23	2.97299	0.00000
4.5000	34.7579	3.27976	5337.04	3.27976	0.00000
15.0000	34.7158	4.26059	5910.85	4.26057	-0.00001
18.5000	34.7068	4.60541	6099.56	4.60541	0.00000
24.0000	34.6969	5.16282	6392.61	5.16284	0.00001
29.0000	34.6914	5.68416	6654.76	5.68416	-0.00000
32.5000	34.6882	6.05617	6835.54	6.05617	-0.00000

$f = \text{Instrument Output(Hz)} * \sqrt{1.0 + \text{WBOTC} * t} / 1000.0$

t = temperature (°C); p = pressure (decibars); $\delta = \text{CTcor}$; $\epsilon = \text{CPcor}$;

Conductivity (S/m) = $(g + h * f^2 + i * f^3 + j * f^4) / (1 + \delta * t + \epsilon * p)$

Residual (Siemens/meter) = instrument conductivity - bath conductivity

