

Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 12120
CALIBRATION DATE: 16-Oct-15

SBE 37 V2 CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -9.908629e-001
h = 1.608731e-001
i = -2.487469e-004
j = 4.352689e-005

CPcor = -9.5700e-008
CTcor = 3.2500e-006
WBOTC = 0.0000e+000

BATH TEMP (ITS-90)	BATH SAL (PSU)	BATH COND (Siemens/m)	INST FREQ (Hz)	INST COND (Siemens/m)	RESIDUAL (Siemens/m)
22.0000	0.0000	0.00000	2484.49	0.00000	0.00000
0.9999	34.6531	2.96333	4960.29	2.96332	-0.00001
4.4999	34.6323	3.26906	5147.95	3.26908	0.00002
14.9999	34.5879	4.24654	5705.93	4.24651	-0.00003
18.4999	34.5777	4.59011	5889.31	4.59013	0.00002
24.0000	34.5661	5.14551	6173.93	5.14551	0.00000
29.0000	34.5591	5.66491	6428.44	5.66491	-0.00000
32.5000	34.5547	6.03551	6603.86	6.03548	-0.00003

$f = \text{INST FREQ} * \sqrt{1.0 + \text{WBOTC} * t} / 1000.0$

Conductivity = $(g + h * f^2 + i * f^3 + j * f^4) / (1 + \delta * t + \epsilon * p)$ Siemens / meter

t = temperature[°C]; p = pressure[decibars]; δ = CTcor; ϵ = CPcor;

Residual = instrument conductivity - bath conductivity

