




Tethys log: 201309301141_201310070703



Bin avreged data (5.4 sec)





Bin avg. depth rat... Display data only


Select data Elevator angle (deg) threshold: 10

Clear selection Depth rate (m/s) threshold: 0.1

Tethys log: 201309301141_201310070703



Bin avreged data (5.4 sec)



Bin avg. depth rat... Display data only

Select data

Clear selection

Tethys log: 201309301141_201310070703

Something caught on the vehicle?

