

**HOBİ Labs, Inc.**

## Instrument Service Document

**Instrument:** HydroShutter-HS

**Serial Number:** SS031014

Institution: MBARI

**Contact:** Jared Figurski

**RMA#:** SS1412A

**Service Performed:**

Internal inspection

### Replace shaft and o-rings

Pressure test after reassembly

**Parts replaced or installed:**[illegible]**Comments:**

Date Completed: 2/11/13

Lead Technician: DRD