



RMA#: H25013A

Completed:

Institution: MBARI

Contact: Jared Figurski

Incoming inspection and test
Full calibration
Outgoing test

Instrument contains a user-installed primary battery that is dead.

[illegible]