



RMA#: H25218A

Completed: 5/1/2019

Institution: MBARI

Contact: Jared Figurski

Functional testing
Standard calibration
Replace zinc anodes

Anodizing of the housing is very worn. It is OK, but we recommend coating it with tape to prevent corrosion.

[illegible]